

HNBR BLUE PADS



DD20-16P



- Now with blue pads in non-marking HNBR

- Working temperature up to 150°C

- Non Textured surface



PB-0170



HNBR BLUE PADS



OFR...95SG



- Now with blue pads in non-marking HNBR

- Working temperature up to 150°C

- Non Textured surface



OFX...

